FIG. 1





FIG. 2











FIG. 4














## BALANCED GLOBE VALVE Irving Erickson et al. Attorney Docket 502226, Telephone (815) 963-7661










FIG. 14

